



American Recovery and Reinvestment Act (ARRA) of 2009

Proof of Qualified Energy Property for Claiming Tax Credits for Residential Heating & Cooling Equipment

The U.S. Internal Revenue Service (IRS) is now providing Consumers with a tax credit on high-efficiency heating and cooling equipment. The Ruud Air Conditioning Division of Rheem Sales Company, Inc. certifies that the models listed on the following pages of this document (if placed in service after December 31, 2008 and before January 1, 2011 in a homeowner's primary residence) meet the criteria of "Qualified Energy Property" as set forth by Section 25C of the Internal Revenue Code.

IMPORTANT NOTICE:

Before filing for a tax credit on one of the following-listed models, Ruud Air Conditioning Division recommends that Consumers consult with a tax professional to review the American Recovery and Reinvestment Act (ARRA) of 2009 and its application in reference to Section 25C of the Internal Revenue Code.

MANUFACTURER:

Ruud Air Conditioning Division
5600 Old Greenwood Road
Fort Smith, AR 72908

EQUIPMENT CLASSIFICATION:

Central Air Conditioner

CERTIFICATION STATEMENT:

Under penalties of perjury, I declare that I have examined this certification statement, and to the best of my knowledge and belief, the facts presented are true, correct, and complete.

A handwritten signature in black ink that reads "Adam Schuster".

Adam Schuster
Manager, Product Marketing & Development
Ruud Air Conditioning Division



American Recovery and Reinvestment Act (ARRA) of 2009

Proof of Qualified Energy Property for Claiming Tax Credits for Residential Heating & Cooling Equipment

TAX CREDIT - 30% OF INSTALLED COSTS, UP TO \$1500

| ARI Ref #. | Model Number | Coil Model Number | Furnace Model Number | EER 95F | SEER | HSPF |
|------------|--------------|-------------------------------|----------------------|---------|-------|------|
| 1069470 | UPRL-024JEZ | RCFM-H*2417A* | UGPL-05?BMK? | 12.80 | 16.50 | 9.50 |
| 3198300 | UPRL-024JEZ | RHPL-HM2421 +RCSM-H*2421A* | | 13.05 | 17.00 | 9.50 |
| 3594627 | UPRL-024JEZ | RCFM-H*2417 | RGFD-07?MCK? | 12.65 | 16.50 | 9.50 |
| 3594628 | UPRL-024JEZ | RCFM-H*2417 | UGFD-07?MCK? | 12.65 | 16.50 | 9.50 |
| 3594632 | UPRL-024JEZ | RCFM-H*2417 | UGGD-06?MCK? | 12.85 | 17.00 | 9.50 |
| 3594635 | UPRL-024JEZ | RCFM-H*2417 | RGGD-07?MCK? | 12.75 | 17.00 | 9.50 |
| 3490801 | UPRL-024JEZ | RCFM-H*2417 | UGRM-07?MAE? | 12.50 | 16.50 | 9.55 |
| 3594644 | UPRL-024JEZ | RCFM-H*2417 | UGJD-07?MCK? | 12.75 | 17.00 | 9.50 |
| 3594633 | UPRL-024JEZ | RCFM-H*2421 | RGGD-06?MCK? | 12.90 | 17.00 | 9.50 |
| 3594653 | UPRL-024JEZ | RCFM-H*2421 | RGPR-05?BMK? | 12.80 | 16.50 | 9.50 |
| 3594655 | UPRL-024JEZ | RCFM-H*2421 | RGPR-07?AMK? | 12.95 | 17.00 | 9.50 |
| 3594656 | UPRL-024JEZ | RCFM-H*2421 | UGPR-07?AMK? | 12.95 | 17.00 | 9.50 |
| 3575927 | UPRL-024JEZ | RCFM-H*2417 | RGRM-06?MAE? | 12.75 | 17.00 | 9.70 |
| 3575926 | UPRL-024JEZ | RCFM-H*2417 | RGRM-04?MAE? | 12.60 | 17.00 | 9.65 |
| 3490800 | UPRL-024JEZ | RCFM-H*2417 | UGRM-06?MAE? | 12.75 | 17.00 | 9.70 |
| 3594649 | UPRL-024JEZ | RCFM-H*2421 | RGLR-07?AMK? | 13.00 | 17.00 | 9.80 |
| 3594662 | UPRL-024JEZ | RCFM-H*2421 | UGRM-07?MAE? | 12.55 | 16.50 | 9.60 |
| 3594663 | UPRL-024JEZ | RHPL-HM2421 +RCSM-H*2421 | | 13.05 | 17.00 | 9.50 |
| 3594623 | UPRL-024JEZ | RCFM-H*2417 | RGFD-06?MCK? | 12.55 | 16.50 | 9.50 |
| 3594648 | UPRL-024JEZ | RCFM-H*2417 | UGLR-07?AMK? | 13.00 | 17.00 | 9.50 |
| 3594629 | UPRL-024JEZ | RCFM-H*2421 | RGFD-07?MCK? | 12.65 | 16.50 | 9.50 |
| 3594650 | UPRL-024JEZ | RCFM-H*2421 | UGLR-07?AMK? | 13.00 | 17.00 | 9.80 |
| 3594657 | UPRL-024JEZ | RCFM-H*2421 | RGRM-04?MAE? | 12.65 | 17.00 | 9.70 |
| 3594661 | UPRL-024JEZ | RCFM-H*2421 | RGRM-07?MAE? | 12.55 | 16.50 | 9.60 |
| 3575928 | UPRL-024JEZ | RCFM-H*2417 | RGRM-07?MAE? | 12.50 | 16.50 | 9.55 |
| 3594624 | UPRL-024JEZ | RCFM-H*2417 | UGFD-06?MCK? | 12.55 | 16.50 | 9.50 |
| 3594640 | UPRL-024JEZ | RCFM-H*2417 | UGJD-06?MCK? | 12.85 | 17.00 | 9.50 |
| 3764328 | UPRL-024JEZ | RCFM-H*2417 | UGTM-06?MAE? | 12.85 | 16.50 | 9.60 |
| 1142430 | UPRL-024JEZ | UHPL-HM2421 +RCSM-H*2421A* | | 13.05 | 17.00 | 9.50 |
| 3764320 | UPRL-024JEZ | RCFM-H*2417 | UGGE-06?MCK? | 13.00 | 17.00 | 9.70 |
| 3764321 | UPRL-024JEZ | RCFM-H*2421 | RGGE-06?MCK? | 13.05 | 17.00 | 9.75 |
| 3764325 | UPRL-024JEZ | RCFM-H*2421 | RGJF-06?MCK? | 13.05 | 17.00 | 9.75 |
| 3764329 | UPRL-024JEZ | RCFM-H*2421 | RGTM-06?MAE? | 12.90 | 17.00 | 9.60 |
| 3594631 | UPRL-024JEZ | RCFM-H*2417 | RGGD-06?MCK? | 12.85 | 17.00 | 9.50 |
| 3594652 | UPRL-024JEZ | RCFM-H*2417 | UGPR-05?BMK? | 12.80 | 16.50 | 9.50 |
| 3594625 | UPRL-024JEZ | RCFM-H*2421 | RGFD-06?MCK? | 12.55 | 16.50 | 9.50 |
| 3594642 | UPRL-024JEZ | RCFM-H*2421 | UGJD-06?MCK? | 12.90 | 17.00 | 9.50 |
| 3594645 | UPRL-024JEZ | RCFM-H*2421 | RGJD-07?MCK? | 12.75 | 17.00 | 9.50 |
| 3764322 | UPRL-024JEZ | RCFM-H*2421 | UGGE-06?MCK? | 13.05 | 17.00 | 9.75 |
| 3594647 | UPRL-024JEZ | RCFM-H*2417 | RGLR-07?AMK? | 13.00 | 17.00 | 9.50 |
| 3594651 | UPRL-024JEZ | RCFM-H*2417 | RGPR-05?BMK? | 12.80 | 16.50 | 9.50 |
| 3594634 | UPRL-024JEZ | RCFM-H*2421 | UGGD-06?MCK? | 12.90 | 17.00 | 9.50 |
| 3594641 | UPRL-024JEZ | RCFM-H*2421 | RGJD-06?MCK? | 12.90 | 17.00 | 9.50 |
| 1069490 | UPRL-024JEZ | RCFM-H*2421A* | UGPL-05?BMK? | 12.80 | 16.50 | 9.50 |
| 3490799 | UPRL-024JEZ | RCFM-H*2417 | UGRM-04?MAE? | 12.60 | 17.00 | 9.65 |
| 3764319 | UPRL-024JEZ | RCFM-H*2417 | RGGE-06?MCK? | 13.00 | 17.00 | 9.70 |



American Recovery and Reinvestment Act (ARRA) of 2009

Proof of Qualified Energy Property for Claiming Tax Credits for Residential Heating & Cooling Equipment

TAX CREDIT - 30% OF INSTALLED COSTS, UP TO \$1500

| ARI Ref #. | Model Number | Coil Model Number | Furnace Model Number | EER 95F | SEER | HSPF |
|------------|--------------|-----------------------------|----------------------|---------|-------|------|
| 3764323 | UPRL-024JEZ | RCFM-H*2417 | RGJF-06?MCK? | 13.00 | 17.00 | 9.70 |
| 3764326 | UPRL-024JEZ | RCFM-H*2421 | UGJF-06?MCK? | 13.05 | 17.00 | 9.75 |
| 3764327 | UPRL-024JEZ | RCFM-H*2417 | RGTM-06?MAE? | 12.85 | 16.50 | 9.60 |
| 3764330 | UPRL-024JEZ | RCFM-H*2421 | UGTM-06?MAE? | 12.90 | 17.00 | 9.60 |
| 3764324 | UPRL-024JEZ | RCFM-H*2417 | UGJF-06?MCK? | 13.00 | 17.00 | 9.70 |
| 3594636 | UPRL-024JEZ | RCFM-H*2417 | UGGD-07?MCK? | 12.75 | 17.00 | 9.50 |
| 3594637 | UPRL-024JEZ | RCFM-H*2421 | RGGD-07?MCK? | 12.75 | 17.00 | 9.50 |
| 3594638 | UPRL-024JEZ | RCFM-H*2421 | UGGD-07?MCK? | 12.75 | 17.00 | 9.50 |
| 3594660 | UPRL-024JEZ | RCFM-H*2421 | UGRM-06?MAE? | 12.80 | 17.00 | 9.70 |
| 3594639 | UPRL-024JEZ | RCFM-H*2417 | RGJD-06?MCK? | 12.85 | 17.00 | 9.50 |
| 3594643 | UPRL-024JEZ | RCFM-H*2417 | RGJD-07?MCK? | 12.75 | 17.00 | 9.50 |
| 3594626 | UPRL-024JEZ | RCFM-H*2421 | UGFD-06?MCK? | 12.55 | 16.50 | 9.50 |
| 3594630 | UPRL-024JEZ | RCFM-H*2421 | UGFD-07?MCK? | 12.65 | 16.50 | 9.50 |
| 3594646 | UPRL-024JEZ | RCFM-H*2421 | UGJD-07?MCK? | 12.75 | 17.00 | 9.50 |
| 3594654 | UPRL-024JEZ | RCFM-H*2421 | UGPR-05?BMK? | 12.80 | 16.50 | 9.50 |
| 3594658 | UPRL-024JEZ | RCFM-H*2421 | UGRM-04?MAE? | 12.65 | 17.00 | 9.70 |
| 3594659 | UPRL-024JEZ | RCFM-H*2421 | RGRM-06?MAE? | 12.80 | 17.00 | 9.70 |
| 1069534 | UPRL-036JEZ | RCFM-H*3621A* | UGPL-07?BRQ? | 12.55 | 16.50 | 8.70 |
| 3594721 | UPRL-036JEZ | RCFM-H*3621 | RGLR-10?BRM? | 12.55 | 16.00 | 8.70 |
| 3594727 | UPRL-036JEZ | RCFM-H*3621 | RGPR-07?BRQ? | 12.55 | 16.50 | 8.70 |
| 3594745 | UPRL-036JEZ | RHPL-HM3621 +RCSM-H*3621 | | 12.75 | 16.50 | 8.70 |
| 3594728 | UPRL-036JEZ | RCFM-H*3621 | UGPR-07?BRQ? | 12.55 | 16.50 | 8.70 |
| 3594722 | UPRL-036JEZ | RCFM-H*3621 | UGLR-10?BRM? | 12.55 | 16.00 | 8.70 |